
# EXHIBIT 14



## USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 3 of 10




- PLMN "311-98" historically used in Baicells Cloud EPC appears to be unregistered in ITU
- To help overcome confusion, Baicells applied for and has received a new HNI/PLMN (314-030)
- · Multiple scenarios need to be tested prior the new PLMN migration
- Commercial networks step-by-step migration is expected to take 3-6 months to ensure network safety




USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 4 of 10

Baicells PLMN Migration Plan



#### USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 5 of 10 Schedule & Milestones 2019 Aug Sept Nov Dec Applied for Consulted iconectiv for new HNI application New HNI Received new PLMN (314-030) · Software development for new PLMN configurations and set-up Cloud EPCs Integration Integrate new cloud EPCs for the new PLMN Test cases for different network elements which involve new Scenarios Testing & PLMN changes Friendly network identifying and solution action plan finalized New software load and monitoring the attached process Friendly Networks Validation Test cases for validation and network stability

# USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 6 of 10



# USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 7 of 10




#### ■ Below test cases should be tested at least:


- MME Pool test for EPC-03 and EPC-04
- eNB upgrade test for all kinds of history versions
- Access to new EPC (new PLMN): Old USIM cards, all kinds of CPE version, new eNB SW version with new PLMN
- Access to new EPC (new PLMN): New USIM cards, all kinds of CPE version, new eNB SW version with new PLMN
- OMC and BOSS functions for new cloud EPC and new USIM cards



## USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 8 of 10



#### USDC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 9 of 10



# US<del>PC IN/ND case 1:20-cv-00037-HAB-SLC document 36-16 filed 04/03/20 page 10 of</del> 10



- Usually, PLMN is configured as customer's own PLMN data, no need to change anything.
- If there are some scenarios configured as invalid PLMN, please follow steps to fix:
  - Change PLMN configurations on EPC
  - Change PLMN configurations on eNodeB
  - Enable CPE's roaming switch

